



Docket No. 05165.1420  
Customer No. 30734

PATENT

10/768032

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,864,433 )

Inventors: Barry A. FETZER, et al. )

Issue Date: March 8, 2005 )

For: CIRCUIT BOARD CLIP APPARATUS AND METHOD )

Certificate  
MAY 13 2005  
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

**ATTENTION: CERTIFICATE OF CORRECTION BRANCH**

Sir:

Pursuant to 35 U.S.C. § 255 and 37 C.F.R. § 1.323, this is a request for the issuance of a Certificate of Correction in the above-identified patent. Two (2) copies PTO Form 1050 are appended. The complete Certificate of Correction involves deleting "is" in Column 10, line 65.

The mistake identified in the appended Form is of a clerical or typographical nature, or of minor character, and resulted from an error made in good faith by applicants.

The Commissioner is hereby authorized to charge Deposit Account No. 50-2036 the amount of \$100 (the fee set forth in 37 C.F.R. § 1.20(a)) to cover the costs of issuing this Certificate. Should any additional fees be needed, authorization is hereby given to charge any fees due in connection with the filing of this request to Deposit Account No. 50-2036.

Issuance of the Certificate of Correction containing the correction is respectfully requested.

Respectfully submitted,

BAKER & HOSTETLER LLP

Leo J. Jennings  
Reg. No. 32,902

Date: 5-6-05

Washington Square, Suite 1100  
1050 Connecticut Avenue, N.W.  
Washington, D.C. 20036  
Phone: (202) 861-1500  
Fax: (202) 861-1783

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO : 6,864,433 B1  
DATED : March 8, 2005  
INVENTOR(S) : Barry A. FETZER, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10  
Line 65, please delete "is".

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP  
Washington Square, Suite 1100  
1050 Connecticut Avenue, N.W.  
Washington, D.C. 20036

PATENT NO. 6,864,433 B1 -----

No. of additional copies

→ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO : 6,864,433 B1  
DATED : March 8, 2005  
INVENTOR(S) : Barry A. FETZER, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10  
Line 65, please delete "is".

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP  
Washington Square, Suite 1100  
1050 Connecticut Avenue, N.W.  
Washington, D.C. 20036

PATENT NO. 6,864,433 B1

No. of additional copies

→ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.